

CDM

environmental engineers, scientists,
planners & management consultants

RECEIVED
EPA REGION VI

1986 JUN 12 AM 10:29

SUPERFUND BRANCH

CAMP DRESSER & MCKEE INC.

3445 Executive Center Drive, Suite 220
Austin, Texas 78731
512 345-6651

May 29, 1986

✓ Mr. John Cochran
U.S. Environmental Protection Agency
First International Building
1201 Elm Street
Dallas, Texas 75270

Doc. Ctrl. No. 143-TS1-EP-CSRE-1

Re: South Cavalcade Street
Weekly Compliance Monitoring Report

Dear John:

Enclosed is a summary of the compliance monitoring activities and field notes for the South Cavalcade Street Site for the week of May 19 through May 23, 1986.

Both Mike Young and Sarah Landtiser have reported to me that field procedures at the South Cavalcade Street Site have improved considerably in the last few weeks. As you will see, few problems are described in the field notes.

One comment in the field notes relates to use of fresh water to flush the screens when installing piezometers. Although this probably doesn't really cause any problem, CDM avoided the need to flush the piezometer casing, and thus to introduce foreign water into the formation, by thoroughly flushing the inside of the augers before the piezometers were placed into the hollow stem.

As you requested, an additional copy of the summary and notes are enclosed for transmission to Koppers.

Sincerely yours,

CAMP DRESSER & MCKEE INC.

Robert S. Kier /ab
Robert S. Kier
Site Manager

002678

0J8